

OIL ANALYSIS REPORT

Color

Bottom

Area | ARCOS-1-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS







no image

no image

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		24 Aug 2023	24 Aug 2023	24 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2

no image

no image


no image

no image



OIL ANALYSIS REPORT

GRAPHS





Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16010768 Test Package : TEST

: Q0004I8P

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Aug 2023 Diagnosed

: 24 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)