

OIL ANALYSIS REPORT

Sample Rating Trend



TAN Auto **AutoTAN-2-QC** Component Oil Fluid

{not provided} (--- GAL)

DIAGNOSIS

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | 2 | |
|--|--|---|---|---|---|---|---|---|---|--|---|--|---|---|---|---|---|---|---|---|---|--|---|---|---|---|---|---|---|---|---|----|---|---|---|---|--|
| | | 1 | n | Г | 1 | Г | 1 | ٢ | T | | ſ | | Г | 1 | a | ٢ | 1 | 1 | 1 | Г | 1 | | n | Т | 1 | ٢ | r | 1 | 1 | 1 | Г | 11 | ٦ | r | T | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |




g2023 Aug2023 Aug2023 Aug2023 Aug2023 Aug2023 Aug2023 Aug2023

| SAMPLE INFORM | IATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Date | | Client Info | | 30 Aug 2023 | 30 Aug 2023 | 29 Aug 2023 |
| Machine Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | | | |
| SAMPLE IMAGES | \$ | method | limit/base | current | history1 | history2 |
| Color | | | | no image | no image | no image |
| Bottom | | | | no image | no image | no image |



OIL ANALYSIS REPORT



WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

