


OIL ANALYSIS REPORT

Sample Rating Trend



ICP Machine Id ARCOS-2-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)


DIAGNOSIS


| SAMPLE INFORM | MATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Date | | Client Info | | 07 Sep 2023 | 07 Sep 2023 | 07 Sep 2023 |
| Machine Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | | | |
| SAMPLE IMAGES | 3 | method | limit/base | current | history1 | history2 |
| Color | | | | no image | no image | no image |
| Bottom | | | | no image | no image | no image |



OIL ANALYSIS REPORT

GRAPHS







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16012279

Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : Q0004IJ2

: 08 Sep 2023

Diagnosed : 08 Sep 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave

Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)