


OIL ANALYSIS REPORT

Sample Rating Trend



ICP Machine Id ARCOS-3-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2	
Sample Date		Client Info		08 Sep 2023	08 Sep 2023	08 Sep 2023	
Machine Age	HR	Client Info		0	0	0	
Oil Age	HR	Client Info		0	0	0	
Oil Changed		Client Info		N/A	N/A	N/A	
Sample Status							
SAMPLE IMAGES	;	method	limit/base	current	history1	history2	

SA	AMPLE IMAGES	method	limit/base	current	history1	history2
Colc	or			no image	no image	no image
Botte	om			no image	no image	no image




OIL ANALYSIS REPORT

GRAPHS



Non-ferrous Metals





Certificate L2367

Laboratory Sample No. Test Package : TEST

Lab Number Unique Number : 16012394

: Q0004IL4

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 08 Sep 2023 Diagnosed

: 08 Sep 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050