


## **OIL ANALYSIS REPORT**

Bottom

Sample Rating Trend



ICP Machine Id ARCOS-2-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

		,,		.,,		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		08 Sep 2023	08 Sep 2023	08 Sep 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				no image	no image	no image

no image


no image

no image



## **OIL ANALYSIS REPORT**

## **GRAPHS**



## Non-ferrous Metals 55 45 40 25



Certificate L2367

Laboratory Sample No. Lab Number

Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : Q0004ILJ Unique Number : 16012708

Received Diagnosed

: 11 Sep 2023 : 11 Sep 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050