


OIL ANALYSIS REPORT

Sample Rating Trend





ICP Machine Id ARCOS-2-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|--------------------|----|-------------|------------|-------------|-------------|-------------|
| Sample Date | | Client Info | | 13 Sep 2023 | 13 Sep 2023 | 13 Sep 2023 |
| Machine Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | | | |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---------------|--------|------------|----------|----------|----------|
| Color | | | no image | no image | no image |
| Bottom | | | no image | no image | no image |




OIL ANALYSIS REPORT

GRAPHS



Non-ferrous Metals





Certificate L2367

Laboratory Sample No.

Lab Number

: Q0004IPO Unique Number : 16013068 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Sep 2023

Diagnosed : 13 Sep 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050