


OIL ANALYSIS REPORT

Sample Rating Trend



ICP Machine Id ARCOS-3-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)


DIAGNOSIS


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Date		Client Info		17 Sep 2023	17 Sep 2023	15 Sep 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS







Certificate L2367

Laboratory Sample No. Lab Number Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Unique Number : 16014046

: Q0004IT4

Received Diagnosed Diagnostician : Wes Davis

: 18 Sep 2023 : 18 Sep 2023 WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave

Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)