




# OIL ANALYSIS REPORT

Sample Rating Trend

UNKNOWN



Area  
**ICP**  
 Machine Id  
**ARCOS-3-AM/900**  
 Component  
**Oil**  
 Fluid  
 {not provided} (--- GAL)





## DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date	Client Info			<b>24 Oct 2023</b>	23 Oct 2023	23 Oct 2023
Machine Age	HR	Client Info		<b>0</b>	0	0
Oil Age	HR	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>N/A</b>	N/A	N/A
Sample Status				<b>---</b>	---	---

SAMPLE IMAGES		method	limit/base	current	history1	history2
Color					<i>no image</i>	<i>no image</i>
Bottom					<i>no image</i>	<i>no image</i>

# OIL ANALYSIS REPORT

## GRAPHS



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** :  
**Lab Number** : Q0004K6I  
**Unique Number** : 16035803  
**Test Package** : TEST

**WEARCHECK LUBRICATION SERVICES QA ACCOUNT**  
 501 Madison Ave  
 Cary, NC  
 US 27513  
 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102  
 F: (919)379-4050