


OIL ANALYSIS REPORT

∩PT Sa







ICP Machine Id ARCOS-3-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		24 Oct 2023	24 Oct 2023	24 Oct 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						


SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16035954 Test Package : TEST

: Q0004K85

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Oct 2023

Diagnosed : 24 Oct 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050