


# **OIL ANALYSIS REPORT**

Sample Rating Trend







## ICP Machine Id ARCOS-1-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		31 Oct 2023	31 Oct 2023	31 Oct 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						


SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



### **OIL ANALYSIS REPORT**

#### **GRAPHS**







Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 16037943 Test Package : TEST

: Q0004KN6

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 31 Oct 2023 Received

Diagnosed : 31 Oct 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050