


OIL ANALYSIS REPORT

Sample Rating Trend



ICP Machine Id ARCOS-3-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION method limit/base current history1 history2 Sample Date Client Info 02 Nov 2023 02 Nov 2023 01 Nov 2023 Machine Age HR Client Info 0 0 0 0 Oil Age HR Client Info 0 0 0 0 Oil Changed Client Info N/A N/A N/A Sample Status							
Machine Age HR Client Info 0 0 0 Oil Age HR Client Info 0 0 0 Oil Changed Client Info N/A N/A N/A	SAMPLE INFORMATION		method	limit/base	current	history1	history2
Oil Age HR Client Info 0 0 0 Oil Changed Client Info N/A N/A N/A	Sample Date		Client Info		02 Nov 2023	02 Nov 2023	01 Nov 2023
Oil Changed Client Info N/A N/A N/A	Machine Age	HR	Client Info		0	0	0
-	Oil Age	HR	Client Info		0	0	0
Sample Status	Oil Changed		Client Info		N/A	N/A	N/A
	Sample Status						
SAMPLE IMAGES method limit/base current history1 history2	SAMPLE IMAGES	3	method	limit/base	current	history1	history2


SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS







Certificate L2367

Laboratory Sample No. Lab Number

: Q0004KU2 Unique Number : 16039160 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 02 Nov 2023 Received

Diagnosed : 02 Nov 2023 Diagnostician : Wes Davis

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)