


## **OIL ANALYSIS REPORT**

Sample Rating Trend



ICP Machine Id ARCOS-3-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)


DIAGNOSIS


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Date		Client Info		03 Nov 2023	03 Nov 2023	03 Nov 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**

## **GRAPHS**







Certificate L2367

Laboratory Sample No. Test Package : TEST

Lab Number

: Q0004KY9 Unique Number : 16039661

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 06 Nov 2023 Received : 06 Nov 2023

Diagnosed Diagnostician : Wes Davis WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050