


## **OIL ANALYSIS REPORT**







# TAN Man TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

### DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		29 Jan 2024	29 Jan 2024	29 Jan 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No. Lab Number

: Q00054RK Unique Number : 16080429

Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 29 Jan 2024

Diagnosed : 29 Jan 2024 Diagnostician : Wes Davis

501 Madison Ave Cary, NC US 27513

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050