

## **OIL ANALYSIS REPORT**

Sample Rating Trend



ICP Machine Id ARCOS-2-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Date		Client Info		29 Jan 2024	29 Jan 2024	29 Jan 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Laboratory Sample No. Lab Number Unique Number : 16081059

: Q000557C

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 29 Jan 2024

Diagnosed : 29 Jan 2024 Diagnostician : Wes Davis

501 Madison Ave Cary, NC US 27513

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050