

# **OIL ANALYSIS REPORT**

# TAN Man **TANMAN-QC**

Component **Oil** Fluid {not provided} (--- GAL)

### DIAGNOSIS



### 70074 Jap2024 Jap204 J


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		30 Jan 2024	30 Jan 2024	30 Jan 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

### Sample Rating Trend



## **OIL ANALYSIS REPORT**

GRAPHS



WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

: 30 Jan 2024

: 30 Jan 2024

T: (919)379-4102

F: (919)379-4050