

## **OIL ANALYSIS REPORT**

## Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

## DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		30 Jan 2024	30 Jan 2024	30 Jan 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

3024 ls-3024 ls-3024 ls-3024 ls-3024 ls-3024 ls-3024 ls-3024



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No. Lab Number

: Q00055N2 Unique Number : 16081625 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 30 Jan 2024

Diagnosed : 30 Jan 2024 Diagnostician : Wes Davis

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050 Contact/Location: WCLS CARY NC ? - WEACARQA