

# **OIL ANALYSIS REPORT**

## Sample Rating Trend





# TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS

TOTAL CONTROL CONTROL CONTROL CONTROL CONTROL CONTROL CONTROL								
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2		
Sample Date		Client Info		30 Jan 2024	30 Jan 2024	30 Jan 2024		
Machine Age	HR	Client Info		0	0	0		
Oil Age	HR	Client Info		0	0	0		
Oil Changed		Client Info		N/A	N/A	N/A		
Sample Status								
CONTAMINATION		method	limit/base	current	history1	history2		
Water		WC Method		NEG	NEG	NEG		
SAMPLE IMAGES		method	limit/base	current	history1	history2		

3024 ls-3024 ls-3024 ls-3024 ls-3024 ls-3024 ls-3024 ls-3024

Water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No. Lab Number

: Q00055SG Unique Number : 16081819 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 30 Jan 2024

Diagnosed : 30 Jan 2024 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave

Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050