


## **OIL ANALYSIS REPORT**

Sample Rating Trend



## TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

			25051 100501	1000001 1000001	1002021 1002021 1002021 10	NEVE I	
	SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
	Sample Date		Client Info		06 Feb 2024	06 Feb 2024	06 Feb 2024
	Machine Age	HR	Client Info		0	0	0
	Oil Age	HR	Client Info		0	0	0
	Oil Changed		Client Info		N/A	N/A	N/A
	Sample Status						
	CONTAMINATION	١	method	limit/base	current	history1	history2
	Water		WC Method		NEG	NEG	NEG
	SAMPLE IMAGES	3	method	limit/base	current	history1	history2
	Color				no image	no image	no image
	Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No.

Lab Number : Q0005KPO Unique Number : 16102674

Test Package : TEST

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 06 Feb 2024 : 06 Feb 2024

: 06 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050 Contact/Location: WCLS CARY NC ? - WEACARQA

T: (919)379-4102