

OIL ANALYSIS REPORT

Bottom

Sample Rating Trend



TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORMA	ATION	method	limit/base	current	history1	history2
Sample Date		Client Info		07 Feb 2024	07 Feb 2024	07 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image

no image

no image

no image



OIL ANALYSIS REPORT

GRAPHS



Report Id: WEACARQA [WUSCAR] Q0005O02 (Generated: 02/14/2024 04:57:04) Rev: 1

Laboratory Sample No.

Lab Number : Q0005O02 Unique Number : 16107243

Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Feb 2024 : 07 Feb 2024

: 07 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Page 2 of 2

Contact: WCLS CARY NC

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Contact/Location: WCLS CARY NC? - WEACARQA