

## **OIL ANALYSIS REPORT**

## Sample Rating Trend



TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

DIAGNOSIS

{not provided} (--- GAL)

		32024 Feb2024	Feb2024 Feb2024	Feb2024 Feb203	24 Feb2024	Feb 2024	
SAMPLE INFORMATION		method	limit/base	CU	irrent	history1	history2
Sample Date		Client Info		08 Feb	2024	08 Feb 2024	08 Feb 2024
Machine Age	HR	Client Info		0		0	0
Oil Age	HR	Client Info		0		0	0
Oil Changed		Client Info		N/A		N/A	N/A
Sample Status							

CONTAMINATION	method	limit/base	current	history1	history2
Water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No.

Lab Number : Q0005PIK Unique Number : 16109479

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 08 Feb 2024

: 08 Feb 2024 : 08 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Test Package : TEST Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050