


OIL ANALYSIS REPORT





TAN Man TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date Machine Age	HR	Client Info		08 Feb 2024 0	08 Feb 2024 0	08 Feb 2024 0
Oil Age	HR	Client Info		0 N/A	0 N/A	0 N/A
Oil Changed Sample Status		Client inio		N/A 	IN/A	IN/A
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Lab Number : Q0005PJ7 Unique Number : 16109502

Received Tested Diagnosed

: 08 Feb 2024 : 08 Feb 2024

: 08 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Test Package : TEST

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Contact: WCLS CARY NC

Report Id: WEACARQA [WUSCAR] Q0005PJ7 (Generated: 02/15/2024 09:08:13) Rev: 1

Contact/Location: WCLS CARY NC ? - WEACARQA