

OIL ANALYSIS REPORT

Bottom

Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

		32024 F802024	Feb2UZ4 Feb2UZ4	FEDZUZ4 FEDZUZ4 FE	802024	
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		08 Feb 2024	08 Feb 2024	08 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image

3024 E457074 E457074 E457074 E457074 E457074 E457074 E457074

no image

no image

no image



OIL ANALYSIS REPORT

GRAPHS



Report Id: WEACARQA [WUSCAR] Q0005PK6 (Generated: 02/15/2024 14:11:39) Rev: 1

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number : Q0005PK6 Unique Number : 16109537

Received Tested Diagnosed : 08 Feb 2024 : 08 Feb 2024

: 08 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 F: (919)379-4050

Page 2 of 2

Contact: WCLS CARY NC

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)