

## **OIL ANALYSIS REPORT**

## Sample Rating Trend



3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074





# TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS

IATION	method	limit/base	current	history1	history2
	Client Info		08 Feb 2024	08 Feb 2024	08 Feb 2024
HR	Client Info		0	0	0
HR	Client Info		0	0	0
	Client Info		N/A	N/A	N/A
J	method	limit/base	current	history1	history2
	WC Method		NEG	NEG	NEG
;	method	limit/base	current	history1	history2
			no image	no image	no image
			no image	no image	no image
	HR HR	Client Info HR Client Info Client Info Client Info Client Info WC Method	Client Info HR Client Info HR Client Info Client Info Client Info WC Method	Client Info  O8 Feb 2024  HR Client Info  O Client Info  Client Info  N/A   I method limit/base current  WC Method NEG  method limit/base current  no image	Client Info   08 Feb 2024   08 Feb 2024



### **OIL ANALYSIS REPORT**

**GRAPHS** 



Laboratory Sample No.

Lab Number : Q0005PKI Unique Number : 16109549

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 08 Feb 2024 : 08 Feb 2024

: 08 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA

Contact: WCLS CARY NC

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)