

OIL ANALYSIS REPORT

Sample Rating Trend

UNKNOWN



TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

		32024 P802024	PEDZUZ4 PEDZUZ4	PEDZUZ4 PEDZUZ4 PEDZUZ4 P	902029	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Date		Client Info		08 Feb 2024	08 Feb 2024	08 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	historv1	historv2

3034 EAS0034 EAS0034 EAS0034 EAS0034 EAS0034 EAS0034 EAS0034

Water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Laboratory

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Lab Number : Q0005PMF Unique Number : 16109618

Received Tested Diagnosed

: 08 Feb 2024 : 08 Feb 2024

: 08 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA