

## **OIL ANALYSIS REPORT**

## Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

DIAGNOSIS

{not provided} (--- GAL)

		72021 100202	1 1000001 1000001	100001 100001 100001	002021	
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		09 Feb 2024	09 Feb 2024	09 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

CONTAMINATION	method	limit/base	current	history1	history2
Water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory

Sample No.

Test Package : TEST

Lab Number : Q0005R0V Unique Number : 16111596

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 09 Feb 2024 : 09 Feb 2024

: 09 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

US 27513 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA