

OIL ANALYSIS REPORT

Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		09 Feb 2024	09 Feb 2024	09 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074

CONTAMINATION	method	limit/base	current	history1	history2
Water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Report Id: WEACARQA [WUSCAR] Q0005R27 (Generated: 02/16/2024 05:17:01) Rev: 1

Laboratory Sample No.

Lab Number : Q0005R27 Unique Number : 16111644

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 09 Feb 2024 : 09 Feb 2024

: 09 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (919)379-4102 F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA