

OIL ANALYSIS REPORT

Sample Rating Trend

UNKNOWN



TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

3,004 100,004 100,004 100,004 100,004 100,004 100,004 100,004							
IATION	method	limit/base	current	history1	history2		
	Client Info		09 Feb 2024	09 Feb 2024	09 Feb 2024		
HR	Client Info		0	0	0		
HR	Client Info		0	0	0		
	Client Info		N/A	N/A	N/A		
1	method	limit/base	current	history1	history2		
	WC Method		NEG	NEG	NEG		
;	method	limit/base	current	history1	history2		
	HR HR	Client Info HR Client Info HR Client Info Client Info Client Info WC Method	Client Info HR Client Info HR Client Info Client Info Client Info WC Method	Client Info	Client Info 09 Feb 2024 09 Feb 2024 HR		

3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074

Water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Laboratory

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Lab Number : Q0005R3M Unique Number : 16111695

Received Tested Diagnosed

: 09 Feb 2024 : 09 Feb 2024 : 09 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (919)379-4102

F: (919)379-4050