

## **OIL ANALYSIS REPORT**

## Sample Rating Trend



3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074

## TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Date		Client Info		09 Feb 2024	09 Feb 2024	09 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number : Q0005R5B Unique Number : 16111756

Test Package : TEST

Received Tested Diagnosed

: 09 Feb 2024 : 09 Feb 2024 : 09 Feb 2024 - Wes Davis

501 Madison Ave

Contact: WCLS CARY NC

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050 Contact/Location: WCLS CARY NC ? - WEACARQA

Cary, NC

US 27513

T: (919)379-4102