


OIL ANALYSIS REPORT

Sample Rating Trend



TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

	SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
	Sample Date		Client Info		10 Feb 2024	10 Feb 2024	10 Feb 2024
	Machine Age	HR	Client Info		0	0	0
	Oil Age	HR	Client Info		0	0	0
	Oil Changed		Client Info		N/A	N/A	N/A
	Sample Status						
	CONTAMINATION	J	method	limit/base	current	history1	history2
	Water		WC Method		NEG	NEG	NEG
	SAMPLE IMAGES	;	method	limit/base	current	history1	history2
	Color				no image	no image	no image
	Bottom				no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number : Q0005S8L

Unique Number : 16113823 Test Package : TEST

Received Tested Diagnosed

: 10 Feb 2024 : 10 Feb 2024

: 10 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

US 27513 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (919)379-4102 F: (919)379-4050