

OIL ANALYSIS REPORT

Sample Rating Trend





TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

JULIA PROJUKA PROJUKA PROJUKA PROJUKA PROJUKA PROJUKA PROJUKA							
SAMPLE INFORMATION		method	limit/base	current	history1	history2	
Sample Date		Client Info		10 Feb 2024	10 Feb 2024	10 Feb 2024	
Machine Age	HR	Client Info		0	0	0	
Oil Age	HR	Client Info		0	0	0	
Oil Changed		Client Info		N/A	N/A	N/A	
Sample Status							
CONTAMINATION		method	limit/base	current	history1	history2	
Water		WC Method		NEG	NEG	NEG	
SAMPLE IMAGES		method	limit/base	current	history1	history2	

3034 EAS0034 EAS0034 EAS0034 EAS0034 EAS0034 EAS0034 EAS0034

Water	WC Method	ľ	NEG	NEG	NEG
SAMPLE IMAGES	method li	imit/base	current	history1	history2
Color		ı	no image	no image	no image
Bottom		,	no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Lab Number : Q0005SAN Unique Number : 16113897

Received Tested Diagnosed

: 10 Feb 2024 : 10 Feb 2024

: 10 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050 Contact/Location: WCLS CARY NC ? - WEACARQA

Report Id: WEACARQA [WUSCAR] Q0005SAN (Generated: 02/17/2024 09:55:14) Rev: 1

Page 2 of 2