

## **OIL ANALYSIS REPORT**

## DT



## TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		10 Feb 2024	10 Feb 2024	10 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number : Q0005SAW

Unique Number : 16113906

Received Tested Diagnosed

: 10 Feb 2024 : 10 Feb 2024 : 10 Feb 2024 - Wes Davis

Contact/Location: WCLS CARY NC ? - WEACARQA

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Test Package : TEST

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050

Contact: WCLS CARY NC