


OIL ANALYSIS REPORT

DT ^{*}







TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORM	ΙΔΤΙΩΝ	method	limit/base	current	history1	history2
SAMPLE INFORMATION		memou	IIIIIIVDase	Current	HISTOLAL	HISTOLYZ
Sample Date		Client Info		10 Feb 2024	10 Feb 2024	10 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	1	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Lab Number : Q0005SC3 **Unique Number** : 16113949

Test Package : TEST

Received Tested Diagnosed

: 10 Feb 2024 : 10 Feb 2024

: 10 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

US 27513 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA

Report Id: WEACARQA [WUSCAR] Q0005SC3 (Generated: 02/17/2024 16:57:17) Rev: 1

Page 2 of 2