

OIL ANALYSIS REPORT

Bottom

Sample Rating Trend

UNKNOW



TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

	12024 Feb2024	Feb2024 Feb2024	Feb2024 Feb2024 Feb2024 Fe	b2024	
SAMPLE INFORMAT	ION method	limit/base	current	history1	history2
Sample Date	Client Info		10 Feb 2024	10 Feb 2024	10 Feb 2024
Machine Age HF	R Client Info		0	0	0
Oil Age HF	R Client Info		0	0	0
Oil Changed	Client Info		N/A	N/A	N/A
Sample Status					
CONTAMINATION	method	limit/base	current	history1	history2
Water	WC Method		NEG	NEG	NEG
SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image

no image

no image

no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory Sample No.

Lab Number : Q0005SF3 Unique Number : 16114057

Received Tested

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 10 Feb 2024 : 10 Feb 2024

Diagnosed : 10 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Test Package : TEST To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050

Report Id: WEACARQA [WUSCAR] Q0005SF3 (Generated: 02/18/2024 00:16:52) Rev: 1

Contact/Location: WCLS CARY NC? - WEACARQA