

OIL ANALYSIS REPORT

Bottom

Sample Rating Trend





TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

		72027 1602027	P802024 P802024	P802024 P802024 P802024 P	102024	
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	1	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Oalar						
Color				no image	no image	no image

3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074

no image

no image

no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Lab Number : Q0005USX Unique Number : 16117244

Received Tested

: 12 Feb 2024 : 12 Feb 2024

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Diagnosed : 12 Feb 2024 - Wes Davis Test Package : TEST Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050