

# **OIL ANALYSIS REPORT**

## Sample Rating Trend



3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074





### TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
			IIIIII DAGO		,	,
Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	1	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



#### **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No.

Lab Number : Q0005UVH

Unique Number : 16117342

Received Tested

: 12 Feb 2024 : 12 Feb 2024 Diagnosed : 12 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

Test Package : TEST To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Report Id: WEACARQA [WUSCAR] Q0005UVH (Generated: 02/18/2024 12:09:07) Rev: 1

Contact/Location: WCLS CARY NC ? - WEACARQA