

# **OIL ANALYSIS REPORT**

## Sample Rating Trend





# TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number : Q0005UW5

Unique Number : 16117366 Test Package : TEST

Received Tested Diagnosed

: 12 Feb 2024 : 12 Feb 2024

: 12 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

US 27513 Contact: WCLS CARY NC

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050