

## **OIL ANALYSIS REPORT**

Sample Rating Trend



ICP Machine Id ARCOS-3-AM/900

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

		72024 160202	4 F802024 F802024	P802024 P802024 P802024 P	002027	
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		12 Feb 2024	09 Feb 2024	09 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. Lab Number : Q0005UY7

**Unique Number** : 16117452 Test Package : TEST

Received Tested

: 12 Feb 2024 : 12 Feb 2024 Diagnosed : 12 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

US 27513 Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA