

## **OIL ANALYSIS REPORT**

Bottom

## Sample Rating Trend



no image

no image

no image

TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

		32024 16020	1602027 1602027	1002027 1002027 1002027 11	02021	
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image

2/0/4 Feb/0/4 Feb/0/4 Feb/074 Feb/074



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Certificate L2367

Laboratory Sample No.

Lab Number : Q0005UYD Unique Number : 16117458

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: 12 Feb 2024 : 12 Feb 2024

: 12 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Test Package : TEST To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050

Report Id: WEACARQA [WUSCAR] Q0005UYD (Generated: 02/18/2024 21:20:43) Rev: 1

Contact/Location: WCLS CARY NC? - WEACARQA