

OIL ANALYSIS REPORT

Bottom

Sample Rating Trend

UNKNOWN



TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

			4 F60ZUZ4 F60ZUZ4	Feb2024 Feb2024 Feb2024 F	802024	
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	1	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES	1	method	limit/base	current	history1	history2
Color				no image	no image	no image

3024 E457074 E457074 E457074 E457074 E457074 E457074 E457074

no image

no image

no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number : Q0005UZB Unique Number : 16117528

Test Package : TEST

Received Tested Diagnosed

: 12 Feb 2024 : 12 Feb 2024 : 12 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (919)379-4102

F: (919)379-4050