

OIL ANALYSIS REPORT

Bottom

Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

CAMPLE INFORM	IATION	اء مالم مما	::		la la ta mud	h:ata0
SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	1	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES	1	method	limit/base	current	history1	history2
Color				no image	no image	no image

2/0/4 Feb/0/4 Feb/0/4 Feb/074 Feb/074

no image

no image

no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory Sample No.

Test Package : TEST

Lab Number : Q0005UZO Unique Number : 16117566

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Tested

: 12 Feb 2024 : 12 Feb 2024

Diagnosed : 12 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Contact/Location: WCLS CARY NC? - WEACARQA

US 27513