

OIL ANALYSIS REPORT

Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
			IIIIII DAGO		,	,
Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	1	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074



OIL ANALYSIS REPORT

GRAPHS



Laboratory Sample No.

Lab Number : Q0005UZU **Unique Number** : 16117573

Received Tested

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 12 Feb 2024 : 12 Feb 2024

Diagnosed : 12 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050

Contact: WCLS CARY NC

Report Id: WEACARQA [WUSCAR] Q0005UZU (Generated: 02/19/2024 01:27:29) Rev: 1

Contact/Location: WCLS CARY NC ? - WEACARQA