

OIL ANALYSIS REPORT

Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORMATION method limit/base current history1 history2 Sample Date Client Info 12 Feb 2024 12 Feb 2024 12 Feb 2024 Machine Age HR Client Info 0 0 0 0 Oil Age HR Client Info 0 0 0 0 Oil Changed Client Info N/A N/A N/A N/A Sample Status CONTAMINATION method limit/base current history1 history2 Water WC Method NEG NEG NEG SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image							
Machine Age HR Client Info 0 0 0 0 Oil Age HR Client Info 0 0 0 0 Oil Changed Client Info N/A N/A N/A Sample Status CONTAMINATION method limit/base current history1 history2 Water WC Method NEG NEG NEG SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image	SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Oil Age HR Client Info 0 0 0 0 Oil Changed Client Info N/A N/A N/A Sample Status CONTAMINATION method limit/base current history1 history2 Water WC Method NEG NEG NEG SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image	Sample Date		Client Info		12 Feb 2024	12 Feb 2024	12 Feb 2024
Oil Changed Client Info Sample Status CONTAMINATION method limit/base current history1 history2 Water WC Method NEG NEG NEG SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image	Machine Age	HR	Client Info		0	0	0
Sample Status CONTAMINATION method limit/base current history1 history2 Water WC Method NEG NEG NEG SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image	Oil Age	HR	Client Info		0	0	0
CONTAMINATION method limit/base current history1 history2 Water WC Method NEG NEG NEG SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image	Oil Changed		Client Info		N/A	N/A	N/A
Water WC Method NEG NEG NEG SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image	Sample Status						
SAMPLE IMAGES method limit/base current history1 history2 Color no image no image no image	CONTAMINATION		method	limit/base	current	history1	history2
Color no image no image no image	Water		WC Method		NEG	NEG	NEG
	SAMPLE IMAGES		method	limit/base	current	history1	history2
Bottom no image no image no image	Color				no image	no image	no image
	Bottom				no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory Sample No.

Test Package : TEST

Lab Number : Q0005V1K **Unique Number** : 16117659

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: 12 Feb 2024 : 12 Feb 2024

: 12 Feb 2024 - Wes Davis

Cary, NC US 27513 Contact: WCLS CARY NC

501 Madison Ave

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

WEARCHECK LUBRICATION SERVICES QA ACCOUNT