


OIL ANALYSIS REPORT

Sample Rating Trend







TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORM	ΙΔΤΙΩΝ	method	limit/base	current	history1	history2
SAMI LE IN ORMATION		metriod	IIIIII Dasc	Carrent	Tilotory	HISTOTYZ
Sample Date		Client Info		13 Feb 2024	13 Feb 2024	13 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	ı	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory Sample No.

Test Package : TEST

Lab Number : Q0005VZB **Unique Number** : 16118949

Received Tested Diagnosed

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: 13 Feb 2024 : 13 Feb 2024

: 13 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA

US 27513

T: (919)379-4102