

# OIL ANALYSIS REPORT

# VOLVO PENTA

## VOLVO PENTA 51220351780 - INBOARD - PORT GEARBOX

Sample No: VPA045287

Oil Type: ATF

### SAMPLE INFORMATION

Sample Number	VPA045287	---	---	---
Sample Date	29 Aug 2022	---	---	---
Machine Hours	459	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	ATTENTION	---	---	---

### SUNCOAST DIESEL MARINE

6341 PORTER ROAD, SUITE 6  
SARASOTA, FL  
US 34240  
Contact: SERVICE MANAGER  
info@suncoastdmi.com  
T: (941)342-0033  
F:

### OIL CONDITION

Visc @ 40°C	cSt	■ 30.7	---	---	---
-------------	-----	--------	-----	-----	-----

### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 11	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ 3	---	---	---

### WEAR METALS

PQ		■ 41	---	---	---
Iron	ppm	● 151	---	---	---
Copper	ppm	● 159	---	---	---
Lead	ppm	■ 4	---	---	---
Tin	ppm	■ 6	---	---	---
Aluminum	ppm	● 10	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	■ 7	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	■ 2	---	---	---
Vanadium	ppm	0	---	---	---

### ADDITIVES

Calcium	ppm	■ 194	---	---	---
Magnesium	ppm	■ 3	---	---	---
Zinc	ppm	■ 164	---	---	---
Phosphorus	ppm	■ 304	---	---	---
Barium	ppm	■ 12	---	---	---
Boron	ppm	■ 126	---	---	---

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Bearing and/or gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP705283  
Unique No: 10115876  
Signed: Doug Bogart  
Report Date: 06 Sep 2022

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

## GRAPHS

