



## GARLAND HAGEN R10401772 VOLVO PENTA 3950008331 - STARBOARD IPS

Sample No: VPA029836

**Oil Type:** VOLVO PENTA GL-5 SAE 75W90

SAMPLE INFORM	IATION			
	IATIUN			
Sample Number		VPA029836	 	
Sample Date		10 May 2024	 	
Machine Hours		41	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		MARGINAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	■82.6	 	
CONTAMINATION	N			
Water	%	<b>△</b> 0.171	 	
Silicon	ppm	12	 	
Sodium	ppm	<b>■</b> 3	 	
Potassium	ppm	3	 	
WEAR METALS				
PQ		■54	 	
Iron	ppm	<b>■</b> 171	 	
Copper	ppm	5	 	
Lead	ppm	0	 	
Tin	ppm	<1	 	
Aluminum	ppm	<1	 	
Chromium	ppm	<b></b>	 	
Molybdenum	ppm	<b>■</b> 0	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■</b> 5	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	7	 	
Magnesium	ppm	<b>167</b>	 	
Zinc	ppm	■0	 	
Phosphorus	ppm	<b>1306</b>	 	
Barium	ppm	■0	 	
Boron	ppm	■333	 	
	1.1.			

Western Branch Diesel, Inc. - VP527273 3504 SHIPWRIGHT ST

PORTSMOUTH, VA US 23703

Contact: GEORGE ROGIC grogic@wbdiesel.com

T: F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a trace of moisture present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP155396Unique No:11023548Signed:Jonathan HesterReport Date:17 May 2024

## **OIL ANALYSIS REPORT**



