

PROBLEM SUMMARY

Sample Rating Trend


ISO

Machine Id KAESER SK 15 5367332 (S/N 1824)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status		ABNORMA	AL NORMAL	ABNORMAL			
Particles >6µm	ASTM D7647 >	>1300 A 12672	1047	4616			
Particles >14μm	ASTM D7647 >	>80 ^ 1543	68	<u></u> ▲ 645			
Particles >21μm	ASTM D7647 >	>20 ^ 279	13	1 36			
Particles >38μm	ASTM D7647 >	>4 ^ 7	0	2			
Oil Cleanliness	ISO 4406 (c) >	>/17/13 🛕 22/21/18	17/13	△ 19/17			

Customer Id: KROFOR Sample No.: KCP48149 Lab Number: 05623845 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

07 Mar 2022 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



16 Aug 2021 Diag: Jonathan Hester

150



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



15 Feb 2021 Diag: Doug Bogart

ISO




No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



KAESER SK 15 5367332 (S/N 1824)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Sap2017 Jan2019 Mar2020 Nov2020 Feb2021 Aug2022 Mar2022 Aug2022						
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP48149	KCP38394	KCP42579
Sample Date				18 Aug 2022	07 Mar 2022	16 Aug 2021
Machine Age	hrs			27952	26366	24646
Oil Age	hrs			1585	3883	2200
Oil Changed				Not Changd	Changed	Not Changd
Sample Status				ABNORMAL	NORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	0	0	0
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	0	<1	<1
Aluminum	ppm	ASTM D5185m	>10	<1	<1	0
Lead	ppm	ASTM D5185m	>10	0	0	0
Copper	ppm	ASTM D5185m	>50	<1	2	1
Tin	ppm	ASTM D5185m	>10	0	0	0
Antimony	ppm	ASTM D5185m				4
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		0	0	<1
Barium	ppm	ASTM D5185m	90	11	0	<1
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	<1
Magnesium	ppm	ASTM D5185m	90	82	67	69
Calcium	ppm	ASTM D5185m	2	<1	0	<1
Phosphorus	ppm	ASTM D5185m		3	3	2
Zinc	ppm	ASTM D5185m		2	6	0
Sulfur	ppm	ASTM D5185m		18547	16492	17466
CONTAMINANTS	}	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	<1	<1	<1
Sodium	ppm	ASTM D5185m		11	13	11
Potassium	ppm	ASTM D5185m	>20	0	<1	2
Water	%	ASTM D6304	>0.05	0.027	0.019	0.028
ppm Water	ppm	ASTM D6304	>500	272.4	190.1	289.6
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4μm		ASTM D7647		34654	3867	13238
Particles >6µm		ASTM D7647	>1300	12672	1047	<u>4616</u>
Particles >14μm		ASTM D7647	>80	<u> </u>	68	△ 645
Particles >21µm		ASTM D7647	>20	<u>^</u> 279	13	△ 136
Particles >38µm		ASTM D7647	>4	<u> </u>	0	2
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u>22/21/18</u>	17/13	△ 19/17
FLUID DEGRADA	ATION	method	limit/base	current	history 1	history 2
<u> </u>						




0.00

OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	TES	method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	46	44.1	43.7	44.2
SAMPLE IMAGES	3	method	limit/base	current	history 1	history 2
Color						
Bottom						







Laboratory Sample No. Lab Number Unique Number : 10103352

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : KCP48149 : 05623845

Received Diagnosed

: 22 Aug 2022 : 24 Aug 2022

Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF, PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) KROGER DISTRIBUTION

2000 ANVIL BLOCK RD FOREST PARK, GA USA 30297

Contact: Service Manager

T: F: