

PROBLEM SUMMARY

Sample Rating Trend


WATER

KAESER 7956489


Component

Compressor

KAESER G-680 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

The filter change at the time of sampling has been noted. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				ABNORMAL					
Water	%	ASTM D6304	>0.05	△ 0.065					
ppm Water	ppm	ASTM D6304	>500	655.2					

Customer Id: WALNOR Sample No.: KCP44039 Lab Number: 05626821 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

WATER



KAESER 7956489

Component

Compressor

KAESER G-680 (--- GAL)

DIAGNOSIS Recommendation

The filter change at the time of sampling has been noted. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a light concentration of water present in the oil. The amount and size of particulates present in the system are acceptable.


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		Ï				
				Aug2022		
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP44039		
Sample Date				16 Aug 2022		
Machine Age	hrs			847		
Oil Age	hrs			847		
Oil Changed				Not Changd		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	0		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>3	0		
Titanium	ppm	ASTM D5185m	>3	0		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>10	2		
Lead	ppm	ASTM D5185m	>10	1		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>10	1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		14		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		0		
Calcium		ASTM D5185m		0		
	ppm	ASTM D5185m		1379		
Phosphorus	ppm					
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		12		
CONTAMINANTS	i	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	<1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304	>0.05	△ 0.065		
ppm Water	ppm	ASTM D6304	>500	△ 655.2		
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4μm		ASTM D7647		1154		
Particles >6µm		ASTM D7647	>1300	156		
Particles >14μm		ASTM D7647	>80	16		
Particles >21µm		ASTM D7647	>20	5		
Particles >38µm		ASTM D7647	>4	1		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>/17/13	17/14/11		
FLUID DEGRADA	TION	method	limit/base	current	history 1	history 2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.33		



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: KCP44039 : 05626821 : 10111342

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 25 Aug 2022 : 26 Aug 2022 Diagnostician : Doug Bogart Test Package : IND 2 (Additional Tests: KF, PrtCount)

4100 DALE EARNHARDT WAY, SUITE 200 NORTHLAKE, TX USA 76262

WALGREENS

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: WALNOR [WUSCAR] 05626821 (Generated: 08/28/2022 16:31:17)

Contact/Location: Service Manager - WALNOR

T: F:

history 2

history

history 2

no image

no image