

PROBLEM SUMMARY

Sample Rating Trend

WATER


Machine Id **6979543 (S/N 1071)**

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC T	EST RE	SULTS				
Sample Status				ABNORMAL	ABNORMAL	
Water	%	ASTM D6304	>0.05	<u> </u>	0.019	
ppm Water	ppm	ASTM D6304	>500	1350	190.2	
Debris	scalar	*Visual	NONE	▲ MODER	NONE	
Appearance	scalar	*Visual	NORML	▲ HAZY	NORML	
Free Water	scalar	*Visual		<u> </u>	NEG	

Customer Id: BEVWAU Sample No.: KCP50592 Lab Number: 05628358 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS Action Date Done By Description **Status** Change Fluid ? Oil and filter change at the time of sampling has been noted. Change Filter ? Oil and filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of ? Alert particles present in this sample.

HISTORICAL DIAGNOSIS

19 Aug 2020 Diag: Jonathan Hester






No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



WATER



6979543 (S/N 1071)

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil. Free water present. There is a light concentration of water present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

			Aug2020	Aug ² 022		
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP50592	KCP10422	
Sample Date				23 Aug 2022	19 Aug 2020	
Machine Age	hrs			1659	500	
Oil Age	hrs			1659	500	
Oil Changed				Changed	Changed	
Sample Status				ABNORMAL	ABNORMAL	
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	<1	<1	
Chromium	ppm	ASTM D5185m	>10	0	0	
Nickel	ppm	ASTM D5185m	>3	<1	0	
Titanium	ppm	ASTM D5185m	>3	0	0	
Silver	ppm	ASTM D5185m	>2	1	<1	
Aluminum	ppm	ASTM D5185m	>10	2	0	
Lead	ppm	ASTM D5185m	>10	0	<1	
Copper	ppm	ASTM D5185m	>50	1	<1	
Tin	ppm	ASTM D5185m	>10	1	0	
Antimony	ppm	ASTM D5185m	>10		0	
Vanadium		ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		<1	0	
	ppm					
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m	0	<1	<1	
Barium	ppm	ASTM D5185m	90	0	14	
Molybdenum	ppm	ASTM D5185m	0	0	<1	
Manganese	ppm	ASTM D5185m	400	1	<1	
Magnesium	ppm	ASTM D5185m	100	11	26	
Calcium	ppm	ASTM D5185m	0	0	8	
Phosphorus	ppm	ASTM D5185m	0	3	16	
Zinc	ppm	ASTM D5185m	0	43	7	
Sulfur	ppm	ASTM D5185m	23500	18622	19231	
CONTAMINANTS	3	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	2	5	
Sodium	ppm	ASTM D5185m		0	0	
Potassium	ppm	ASTM D5185m	>20	0	4	
Water	%	ASTM D6304	>0.05	<u> </u>	0.019	
ppm Water	ppm	ASTM D6304	>500	1350	190.2	
FLUID CLEANLIN	NESS	method	limit/base	current	history 1	history 2
Particles >4μm		ASTM D7647			11035	
Particles >6µm		ASTM D7647	>1300		▲ 3018	
Particles >14µm		ASTM D7647	>80		25	
Particles >21μm		ASTM D7647	>20		5	
Particles >38µm		ASTM D7647	>4		0	
Particles >71µm		ASTM D7647	>3		0	
Oil Cleanliness		ISO 4406 (c)	>/17/13		△ 19/12	
FLUID DEGRADA	ATION	method	limit/base	current	history 1	history 2
A	1/011/	10T11 D0015				




OIL ANALYSIS REPORT




VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	▲ MODER	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	▲ HAZY	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.05	0.2%	NEG	
Free Water	scalar	*Visual		<u> </u>	NEG	
FLUID PROPERT	TES	method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	45	44.1	43.3	
SAMPLE IMAGES	3	method	limit/base	current	history 1	history 2


Color	no image
Bottom	no image
ODADUO	

GRAPHS



copper copper copper tin	J								
naman lead	J								
						ocity @ 409C			









Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10112879

: KCP50592 : 05628358

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

Diagnosed

: 26 Aug 2022 : 30 Aug 2022

Diagnostician : Angela Borella

Test Package: IND 2 (Additional Tests: KF, PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

BEVCO PRECISION MFG

21320 DORAL RD WAUKESHA, WI USA 53186

Contact: Service Manager

T:

F: