

PROBLEM SUMMARY

Sample Rating Trend

ISO

Machine Id


KAESER BSD 50T 5573311 (S/N 1259)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status			ABNORMAL	ATTENTION	NORMAL		
Particles >6µm	ASTM D7647	>1300	<u> </u>	<u>▲</u> 1771	594		
Particles >14μm	ASTM D7647	>80	610	<u>123</u>	13		
Particles >21µm	ASTM D7647	>20	<u> </u>	△ 32	3		
Oil Cleanliness	ISO 4406 (c)	>/17/13	22/20/16	<u></u> 18/14	16/11		

Customer Id: AMAEDG Sample No.: KCP50579 Lab Number: 05632373 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

11 Feb 2022 Diag: Don Baldridge

ISO



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



14 Jan 2021 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



15 Jul 2020 Diag: Don Baldridge

150



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service





OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

KAESER BSD 50T 5573311 (S/N 1259)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of particulates present in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		Mar2017	Nov2017 May2019	Feb 2020 Jan 2021	Aug 2022	
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP50579	KCP38568	KC90340
Sample Date				15 Aug 2022	11 Feb 2022	14 Jan 2021
Machine Age	hrs			25248	23016	17799
Oil Age	hrs			2232	5217	0
Oil Changed				Not Changd	Changed	Changed
Sample Status				ABNORMAL	ATTENTION	NORMAL
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	0	<1	<1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	<1	<1	<1
Aluminum	ppm	ASTM D5185m	>10	<1	<1	<1
Lead	ppm	ASTM D5185m	>10	<1	0	<1
Copper	ppm	ASTM D5185m	>50	<1	2	<1
Tin	ppm	ASTM D5185m	>10	<1	<1	0
Antimony	ppm	ASTM D5185m			<1	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		0	5	10
Barium	ppm	ASTM D5185m	90	0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	<1
Magnesium	ppm	ASTM D5185m	90	75	75	71
Calcium	ppm	ASTM D5185m	2	0	<1	0
Phosphorus	ppm	ASTM D5185m		2	2	0
Zinc	ppm	ASTM D5185m		4	10	5
Sulfur	ppm	ASTM D5185m		18586	16797	15995
CONTAMINANTS	3	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	1	<1	<1
Sodium	ppm	ASTM D5185m		9	13	12
Potassium	ppm	ASTM D5185m	>20	6	6	8
Water	%	ASTM D6304		0.024	0.021	0.018
ppm Water	ppm	ASTM D6304	>500	241.7	214.7	181.8
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4µm		ASTM D7647		25844	6031	3276
Particles >6µm		ASTM D7647	>1300	<u></u> 8382	<u>▲</u> 1771	594
Particles >14μm		ASTM D7647	>80	<u>▲</u> 610	<u>▲</u> 123	13
Particles >21μm		ASTM D7647	>20	<u>^</u> 90	▲ 32	3
Particles >38μm		ASTM D7647	>4	3	1	0
Particles >71µm		ASTM D7647	>3	1	0	0
Oil Cleanliness		ISO 4406 (c)	>/17/13	22/20/16	<u>▲</u> 18/14	16/11
FLUID DEGRADA	ATION	method	limit/base	current	history 1	history 2


Page 3 of 4



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	LIGHT	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	46	43.6	44.3	43.6
SAMPLE IMAGE	S	method	limit/base	current	history 1	history 2
Color						
Bottom						





Laboratory Sample No.

Lab Number

: KCP50579 : 05632373 Unique Number : 10116894

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 01 Sep 2022 Diagnosed

: 03 Sep 2022 Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

AMAZON FULFILLMENT 19451 S WAVERLY RD

EDGERTON, KS USA 66021

Contact:

T: F:

Report Id: AMAEDG [WUSCAR] 05632373 (Generated: 09/03/2022 12:39:08)

Contact/Location: ? ? - AMAEDG