

PROBLEM SUMMARY

Sample Rating Trend



Machine Id


KAESER ASD 40T 6008069 (S/N 1279)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

| PROBLEMATIC TEST RESULTS | | | | | | | | |
|--------------------------|--------------|---------|-----------------|-------------------|----------|--|--|--|
| Sample Status | | | ABNORMAL | ABNORMAL | ABNORMAL | | | |
| Particles >6µm | ASTM D7647 | >1300 | 2638 | <u>^</u> 6295 | 1122 | | | |
| Oil Cleanliness | ISO 4406 (c) | >/17/13 | 21/19/13 | 1 21/20/17 | ▲ 17/16 | | | |

Customer Id: AMAEDI Sample No.: KC106158 Lab Number: 05646069 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

25 May 2022 Diag: Jonathan Hester

ISO



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



24 Feb 2022 Diag: Don Baldridge

ISO



No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



31 Aug 2021 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

KAESER ASD 40T 6008069 (S/N 1279)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

Fluid

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

| | | 4pr2018 Oc | 2018 Jun2019 Dec20 | 19 Sep2020 Mar2021 Feb20 | 222 Sep 2022 | • |
|-----------------|--------|-------------|--------------------|--------------------------|---------------|-------------|
| SAMPLE INFORT | MATION | method | limit/base | current | history 1 | history 2 |
| Sample Number | | | | KC106158 | KC104846 | KC103673 |
| Sample Date | | | | 14 Sep 2022 | 25 May 2022 | 24 Feb 2022 |
| Machine Age | hrs | | | 20104 | 18107 | 16865 |
| Oil Age | hrs | | | 3239 | 1242 | 159 |
| Oil Changed | | | | Not Changd | Not Changd | Changed |
| Sample Status | | | | ABNORMAL | ABNORMAL | ABNORMAL |
| WEAR METALS | | method | limit/base | current | history 1 | history 2 |
| Iron | ppm | ASTM D5185m | >50 | 0 | 0 | 0 |
| Chromium | ppm | ASTM D5185m | >10 | 0 | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >3 | 0 | 0 | 0 |
| Titanium | ppm | ASTM D5185m | >3 | 0 | 0 | 0 |
| Silver | ppm | ASTM D5185m | >2 | 0 | 0 | <1 |
| Aluminum | ppm | ASTM D5185m | >10 | <1 | <1 | <1 |
| Lead | ppm | ASTM D5185m | >10 | 0 | 1 | 0 |
| Copper | ppm | ASTM D5185m | >50 | 4 | 1 | 3 |
| Tin | ppm | ASTM D5185m | >10 | <1 | <1 | 0 |
| Antimony | ppm | ASTM D5185m | | | | |
| Vanadium | ppm | ASTM D5185m | | 0 | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | 0 | 0 | 0 |
| ADDITIVES | | method | limit/base | current | history 1 | history 2 |
| Boron | ppm | ASTM D5185m | | 0 | <1 | 0 |
| Barium | ppm | ASTM D5185m | 90 | 2 | 23 | 46 |
| Molybdenum | ppm | ASTM D5185m | | 0 | 0 | 0 |
| Manganese | ppm | ASTM D5185m | | 0 | 0 | 0 |
| Magnesium | ppm | ASTM D5185m | 90 | 54 | 84 | 82 |
| Calcium | ppm | ASTM D5185m | 2 | <1 | 1 | 4 |
| Phosphorus | ppm | ASTM D5185m | | 3 | 9 | 4 |
| Zinc | ppm | ASTM D5185m | | 11 | 2 | 9 |
| CONTAMINANTS | 3 | method | limit/base | current | history 1 | history 2 |
| Silicon | ppm | ASTM D5185m | >25 | 1 | 1 | <1 |
| Sodium | ppm | ASTM D5185m | | 17 | 16 | 11 |
| Potassium | ppm | ASTM D5185m | >20 | 2 | 0 | <1 |
| Water | % | ASTM D6304 | >0.05 | 0.023 | 0.032 | 0.016 |
| ppm Water | ppm | ASTM D6304 | >500 | 238.1 | 328.1 | 164.8 |
| FLUID CLEANLIN | NESS | method | limit/base | current | history 1 | history 2 |
| Particles >4µm | | ASTM D7647 | | 11979 | 15330 | 3536 |
| Particles >6μm | | ASTM D7647 | >1300 | <u>^</u> 2638 | △ 6295 | 1122 |
| Particles >14μm | | ASTM D7647 | | 78 | △ 690 | ▲ 369 |
| Particles >21μm | | ASTM D7647 | >20 | 8 | <u>120</u> | <u></u> 182 |
| Dankialaa 00 | | ACTM D7047 | | ^ | A C | A 10 |

ASTM D7647 >4

ASTM D7647 >3

ISO 4406 (c)

method

mg KOH/g ASTM D8045 0.4

0

0

0.33

21/19/13

current

>--/17/13

limit/base

Particles >38µm

Particles >71µm

Oil Cleanliness

Acid Number (AN)

FLUID DEGRADATION

history 1

<u></u> 6

0

21/20/17

0.35

history 2

<u>12</u>


▲ 17/16

0.35




0.00

OIL ANALYSIS REPORT



| VISUAL | | method | limit/base | current | history 1 | history 2 |
|-------------------------|--------|-----------|------------|---------|-----------|-----------|
| White Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | NONE | NONE | NONE |
| Silt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Debris | scalar | *Visual | NONE | LIGHT | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Appearance | scalar | *Visual | NORML | NORML | NORML | NORML |
| Odor | scalar | *Visual | NORML | NORML | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.05 | NEG | NEG | NEG |
| Free Water | scalar | *Visual | | NEG | NEG | NEG |
| FLUID PROPERT | IES | method | limit/base | current | history 1 | history 2 |
| Visc @ 40°C | cSt | ASTM D445 | 46 | 44.6 | 44.1 | 43.4 |
| SAMPLE IMAGES | 3 | method | limit/base | current | history 1 | history 2 |
| Color | | | | | | |







Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10140608

: KC106158 : 05646069 Test Package : IND 2

Bottom

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 20 Sep 2022 : 21 Sep 2022 Diagnostician : Doug Bogart

Contact: Service Manager

AMAZON EDISON LGA-9

2170 ROUTE 27

EDISON, NJ

USA 08817

T:

F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)